

6592542

B1SB9040



2-Cyle / 4-Cycle Primer Bulbs Variety Pack

Paquete variado de bulbos cebadores
para 2 tiempos/4 tiempos

Manufactured for / Fabricado para

ATI Products Inc.

5100-H W. WT Harris Blvd

Charlotte, NC 28269

**A variety pack of primer bulbs for handheld equipment
- Qty 3 (1 each of 3 different sizes)**

**Fits Bolens, Craftsman, Homelite, Husqvarna, John
Deere, Ryan, Ryobi, Stihl, Troy-Bilt, Yard-Machines, and
Yard-Man**

Fits all 2-cycle and 4-cycle Zama carburetors - Zama (0057004). Fits models HDA and WYK carburetors that require a .680" ID x .912" OD - Walbro (188-13). Fits models WA, WT, WY, WYJ, WYK, WYL, WYP, and WZ carburetors that require a .755" OD and .560" HT primer bulb - Walbro (188-12).

For more details, refer to the installation instructions in your operator's manual.

**Paquete surtido de bulbos cebadores para equipos de mano -
Cant. 3 (1 de cada 3 tamaños)**

**Sirve para equipos Bolens, Craftsman, Homelite, Husqvarna,
John Deere, Ryan, Ryobi, Stihl, Troy-Bilt, Yard-Machines y
Yard-Man**

Sirve para todo carburador de 2 y de 4 tiempos - Zama (0057004). Sirve para carburadores de modelos HDA y WYK que requieren un diám. interno de 0.680" y diám. externo de 0.912" - Walbro (188-13). Sirve para carburadores de modelos WA, WT, WY, WYJ, WYK, WYL, WYP y WZ que requieren un bulbo cebador de 0.755" de diám. ext. y 0.560" de alto - Walbro (188-12).

For more details, refer to the installation instructions in your operator's manual.



WARNING: Cancer and Reproductive Harm - www.P65Warnings.ca.gov

AVERTISSEMENT: Cancer et Troubles de l'appareil reproducteur - www.P65Warnings.ca.gov

ADVERTENCIA: Cáncer y Daño Reproductivo - www.P65Warnings.ca.gov



Made in China / Hecho en China