


ASSEMBLY INSTRUCTIONS:


IMPORTANT: Turn off the power at the main fuse or circuit breaker box before starting installation.

STEP 1: Tighten the long mounting screws(D)2 threaded holes in the . onto the ceiling outlet box by the short.

STEP 2: Strip 3/4in. of insulation from wire ends, Twist stripped ends together with pliers, black to black(Live) and white to white(neutral). Attach copper wire to ground wire. Helpful hint: if necessary, attach copper ground wire to grounded junction box.



STEP 3: Attach wire nuts(F) to the wires. Tape wire nuts and wires together.



STEP 4: Place the fixture(A) over the outlet box. Allow heads of the long mounting screws(D) to go through the large ends of the key holes. Twist fixture(A) a little bit clockwise until the heads of the long mounting screws slide into the narrow ends of the key holes in place. Tighten the long screws(D) to fix the fixture pan(A)

STEP 5: Screw Nipple(G) onto the connector (H) and fix it to keep an appropriate length for next installation.

STEP 6: Put the glass shade(B) over the fixture and let the nipple(G) go through the glass shade .

STEP 7: Install the cap(I) on the glass shade(B) fixing together by nut(J).

