



VEVOR

0.0.0.0

RUN Hz A V F/R



F/R

ESC



RUN

SET



STOP

WARNING
1. Risk of electric shock.
2. Read manual before installing.
3. Wait 5 minutes for capacitor discharge
after disconnecting power supply.



5MINUTES

H100-3S2-1B
POWER: 3KW
INPUT: 3PH 220V 50/60Hz
1PH 220V 50/60Hz
OUTPUT: 3PH 0-220V 14A 0-1000HZ



NO21102100036 013