




VELUX®




PAC/PAD/PAH






VAS 452184-2012-02







1







2









3



4



5





VELUX®

USA: VELUX America Inc.
1-800-88-VELUX

CDN: VELUX Canada Inc.
1 800 88-VELUX (888-3589)



AUS: VELUX Australia Pty. Ltd
1300 859 856

NZ: VELUX New Zealand Ltd.
09-6344 126




J: VELUX-Japan Ltd.
0570-00-8145

www.velux.com





6




7




8





9



10



11





ZXT 200

