





# ASSEMBLY INSTRUCTIONS

**Tools Needed:** screwdriver or power drill (optional)


**CAUTION:** When assembling table, **DO NOT** completely tighten bolts & nuts until all parts & holes are properly aligned.

For missing hardware please contact [customerservice@shineco.com](mailto:customerservice@shineco.com)


## PARTS LIST

	<b>A</b> 1 PC		<b>B</b> 2 PC		<b>C</b> 2 PC		<b>D</b> 8 PC
							Stainless Steel Screw (6.3X40 m/m)


### STEP 1




### STEP 2



### STEP 3



### STEP 4



### STEP 5

**TIGHTEN ALL NUTS AND BOLTS WHEN YOU ARE COMPLETELY DONE ASSEMBLING THE TABLE.**