


BE188600TX
IRON/WICKER STORAGE
BAKER'S RACK
Assembly Instructions



For assistance with assembly contact:
Southern Enterprises Inc.
Customer Service 1-800-633-5096
service@seidal.com
www.seidal.com

12585



IRON/WICKER STORAGE BAKER'S RACK

Parts List

Please review all parts and hardware before disposing of any packaging. Call Customer Service if missing hardware. Using a screw that is too long will cause damage. Before beginning assembly, separate each type of screw. Carefully study the screw diagrams below. You may receive extra hardware with your unit.


A. Upper Back Panel	Quantity of 1	B. Bottom Back Panel	Quantity of 1	C. Left Side Panel	Quantity of 1
D. Right Side Panel	Quantity of 1	E. Metal Cross Bar	Quantity of 2	F. Divider Tube	Quantity of 1
G. Wood Top Panel	Quantity of 1	H. Top Side Panel	Quantity of 2		
J.TIP-END-Shelf-Frame	Quantity of 2	K. Shelf-Frame	Quantity of 2	L. Wire Shelf	Quantity of 2
M. Wicker Basket	Quantity of 4	N.Basket Bottom Panel	Quantity of 4	1. Bolt	Quantity of 22
2.Short Bolt 1/4"**1/2" L	Quantity of 2	3.Long Bolt 1/4"**2-1/4" L	Quantity of 4	4.Allen Wrench	Quantity of 1

Care and Cleaning Instructions:

Before using, wipe with a clean, dry cloth. Avoid rubbing or scratching the surface with rough or abrasive objects.

For replacement parts or questions, please Call Customer Service at 1-800-633-5096
Do not return product to store, please call Manufacturer for assistance, questions or Parts.

Assembly Tool Required
No.2 Phillips Screwdriver (Not Included)



IRON/WICKER STORAGE BAKER'S RACK

Assembly Instructions




Figure 1

Assembly Instructions: Unpack and lay parts on clean, padded surface like carpet or blanket. Check that you have all parts indicated on the front page.

Please insert the Bolts (1) through holes on Side Panel (C,D) to attach Bottom Back Panel (B) and both Metal Cross Bars (E), by Wrench (4). The small RING on inner side of both side panels should be facing inside.

Please insert Bolts (1) through holes on both Metal Cross Bars(E) to connect Divider Tube (F) with the arrow pointing down in between, by Wrench (4).




Figure 2

Please attach Upper Back Panel (A) onto both side panel (C,D) and then please tighten both parts using Short Bolts (2) by Wrench (4).

Attach Wood Top Panel (G) onto the Left Side Panel (C)& Right Side Panel (D) .

IRON/WICKER STORAGE BAKER'S RACK

Assembly Instructions





Figure 3



Please insert Bolt (1) through holes on back-side of Upper Back Panel (A) to tighten both top side panels (H) by Wrench (4).

Please insert Long Bolt (3) through holes on both Side Panels (C)&(D) & Wood Top Panel (G) to tighten both Top Side Panels (H) in position by Wrench (4).

Please insert Bolt (1) through holes on side of both Top Side Panels (H) to tighten both Wire Shelves (L), by Wrench (4)

Attach TIP-END-Shelf-Frame (J) to position by hanging its hook to bottom-bar of Bottom Back Panel (B) mean while with its TIP-END goes into the small RINGS on inner side of both Side Panels (C)(D), and Divider Tube (F).

Please attach Shelf-Frame (K) onto between bottom back panel(B) and metal cross bar(E) by hangs

Now please adjust all parts and tighten all bolts from above steps by wrench(4)

Please put Basket Bottom Panels (N) into Wicker Baskets (M) by hands.

Then put the complete baskets onto Shelf-Frames (J) (K).

Now your Bakers' rack is ready to use