












1  M6*50 x 8	2  M6*45 x 8	3  M6*30 x 4	
4  x 16	5  x 16	6  x 4	7  x 1

1


The screw is installed to nearly 50%



2		4PCS
4		4PCS
5		4PCS

2


The screw is installed to nearly 50%



2		4PCS
4		4PCS
5		4PCS


3

3



4


The screw is installed to nearly 50%



1		8PCS
4		8PCS
5		8PCS

4


5



The screw is installed to nearly 100%

3		4PCS
3		4PCS

6



5