






Parts Assembly

Duro Two Handle Widespread Lavatory Faucet, SLW-3612-1.5, SLW-3622-1.5

For faucets purchased after Nov. 2013



Replacement Parts

Part Number	Item
RL-149	Handle assembly handle (2) screw (2) escutcheon (2) 
RL-232 (-H2)	Lever handle assembly handle (2) screw (2) escutcheon (2) 
RL-231 (-H3)	Blade handle assembly handle (2) screw (2) escutcheon (2) 
LN-15* FLR-110-1.5* FLR-110-1.0*	Aerator & retainer flow rates 2.2 gpm (8.3L /min) 1.5 gpm (5.7L /min) 1.0 gpm (3.8L /min) washer aerator retainer 
KN-114 (hot) OFF = CW KN-113 (cold) OFF = CCW	Valve cartridge 
RL-148	Mounting hardware kit retainer (2) gasket (2) flex hose (2) 
RL-150*	Lift rod 
RL-154*	Pop-up drain 

Ordering replacement parts:

Call Symmons customer service at (800) 796-6667, M-F 7:30 am - 7:00 pm EST or check our website at www.symmons.com for a list of Symmons distributors.

* Note: When ordering replacement parts for faucets with an optional decorative finish, append appropriate three letter suffix code to part numbers marked with an asterisk (*).