





Hardware List

A



X12

B




X12

C




X12

D




X8

E




X2

F




X2

G





X4

H





X24



Parts List






1




2



3



4




A



X4 pcs

B




X4 pcs

C



X4 pcs

5




A



X4 pcs

B




X4 pcs

C



X4 pcs

6




C





X4 pcs

D




X4 pcs


7




8



9



F



X2 pcs