




# Dressing table instructions




# Hardware list




A x1




B1 x1




B2 x1




C x2




D x1




E1 x2




E2 x1




F x2




G1 x1



G2 x1




H x1




I x3


# Hardware list




J1x3




J2x3




Kx3




Lx3




Mx2




Nx4











Ox4



Px1



Qx1




|                             |                                                                                     |        |                                            |                                                                                       |        |
|-----------------------------|-------------------------------------------------------------------------------------|--------|--------------------------------------------|---------------------------------------------------------------------------------------|--------|
| Parts list                  |                                                                                     |        |                                            |                                                                                       |        |
| ①                           |    | 49 Pcs | ②                                          |    | 40 Pcs |
| Two in one screw (35*6.7mm) |                                                                                     |        | Three in one nut (10x14mm)                 |                                                                                       |        |
| ③                           |    | 14 Pcs | ④                                          |    | 2 Pcs  |
| Wood chipping (6x30mm)      |                                                                                     |        | Corner code screw(3.5x10mm)                |                                                                                       |        |
| ⑤                           |  | 14 Pcs | ⑥                                          |  | 40 Pcs |
| Self tapping wire(3.5x30mm) |                                                                                     |        | Self tapping wire(3.5x16mm)                |                                                                                       |        |
| ⑦                           |  | 10 Pcs | ⑧                                          |  | 1 Pc   |
| Cross screw (6x30mm)        |                                                                                     |        | Handle & screw(4x32mm)                     |                                                                                       |        |
| ⑨                           |  | 3 Pcs  | ⑩                                          |  | 2 Pcs  |
| Handle & screw(4x18mm)      |                                                                                     |        | Movable guide rail                         |                                                                                       |        |
| ⑪                           |  | 2 Pcs  | ⑫                                          |  | 1 Pc   |
| Iron guide rail             |                                                                                     |        | Double head screwdriver(Cross & flat head) |                                                                                       |        |
| ⑬                           |  | 1 Pc   |                                            |                                                                                       |        |
| The power adapter           |                                                                                     |        |                                            |                                                                                       |        |

## Step 1

①




③



## Step 2

(G1)



(G2)




## Step 3

②




x 4

Ⓒ<sub>1</sub>




Ⓒ<sub>2</sub>

## Step 4




Step 5



Step 6

|   |                                                                                           |
|---|-------------------------------------------------------------------------------------------|
| ② |  x 4 |
| ③ |  x 6 |





Step 7 x3

6




x 4





Install at the pilot hole.

Step 8 x3


1



x 4



Step 9 x3




Step 10 x3

1




x 8



Step 9

x3





Step 10

x3

⑤



x 4





Step 11

X3

9



X 1





8

Step 12

8




X 1






8

## Step 13



## Step 14



|   |                                                                                           |
|---|-------------------------------------------------------------------------------------------|
| ⑥ |  x 8 |
| ④ |  x 2 |



Install at the pilot hole.



## Step 15

①




## Step 16

①




Step 17




Step 18

|   |                                                                                      |     |
|---|--------------------------------------------------------------------------------------|-----|
| 2 |  | x 8 |
|---|--------------------------------------------------------------------------------------|-----|



## Step 19




## Step 20


②




x 4



## Step 21



## Step 22





Step 23

2



x 4




Step 24

7





x 2

10



x 1




## Step 25

⑦




x 4



⑪



x 2



## Step 26



The iron frame is lowered downward,  
and then the mirror is installed.


## Step 27

⑦




x 2

⑩




x 1





## Step 28

⑬



x 1





## Step 29

⑥



x 16



⑥x4

Install at the pilot hole.

## Step 30

