

AC037 Assembling



A X1




B X1




C X1

1



PLEASE REMOVE BLACK
CAP FROM GAS LIFT.

B




2




A

C



3



Article/Tell	Pieces/Anzahl	Article/Tell	Pieces/Anzahl
A	1		
B	1		
C	1		