















INSTRUCTION MANUAL




 1 x 2PCS		 2 x 2PCS	
 C x 2PCS		 D x 2PCS	
 E x 2PCS		 F x 2PCS	
 I x 4PCS		 H x 2PCS	
 J x 5PCS		 K x 5PCS	
 L x 4PCS	 A x 4PCS	 B x 1PC	 G x 14PCS
 M6x15mm P1 x 46PCS	 M6x45mm P2 x 32PCS	 M6x70mm P3 x 6PCS	 M6x40mm P4 x 1PC
 Q x 1PC	 R x 53PCS	 O x 1PCS	 M x 10PCS
 N x 4PCS	 N1 x 3PCS	 Y x 4PCS	 V x 1PC

			
S x 1PC	T x 16PCS	U x 1PC	W x 1PC


STEP 1




STEP 2




STEP 3




STEP 4




STEP5



STEP6



STEP7



STEP8

