














MONTAGEANLEITUNG

$\varnothing 15 \times 12$  A x 34	$\varnothing 7 \times 35$  B x 34	$\varnothing 8 \times 30$  C x 14	$\varnothing 3.5 \times 14$  D x 40	$\varnothing 4 \times 16$  E x 18
4mm  F x 4	7.8x38  G x 2	$\varnothing 4 \times 40$  H x 24	62x40x18x1.2  I x 2	 J x 10
$\varnothing 3 \times 16$  K x 10	334x15x15  L x 4	CL 14"  CR  x4	DL 14"  DR  x4	






SCHRITT 1

Bx14
Dx16
CLx4
CRx4




SCHRITT 2

Ax7
Cx3




SCHRITT 3




SCHRITT 4

Ax7
Cx3




SCHRITT 5

Cx4
Hx6




SCHRITT 6




SCHRITT 7

Bx4
Ex2
Fx2
Ix2




SCHRITT 8

Ax4
Cx4




SCHRITT 9

Jx10
Kx10





SCHRITT 10

Ex16









SCHRITT 11

Fx2
Gx2
Hx2




SCHRITT 12

Ax16
Bx16




SCHRITT 13








SCHRITT 14

Hx16




SCHRITT 15

Dx24
DLx4
DRx4
Lx4



SCHRITT 16



SCHRITT 17

