




ASSEMBLY INSTRUCTION




Part List




① x 1




② x 1




③ x 1




④ x 1




⑤ x 1




⑥ x 1




⑦ x 1



⑧ x 1




⑨ x 1



⑩ x 2

Part List


11 x 1




12 x 1




13 x 1




14 x 1




15 x 2




16 x 1



17 x 1




18 x 2



Hardware List


Ⓐ x 38




Ⓑ x 38




Ⓒ x 36



Ⓓ x 4



Ⓔ x 12




Ⓕ x 2




Ⓖ x 6




Ⓗ x 3



Ⓘ x 26




Ⓙ x 12




Tip Restraint Kit


a x4




b x4




c x2




d x2




step 1




step 2




step 3





step 4




step 5




x2




step 6




step 7




step 8




step 9




step 10




step 11




step 12




step 13




step 14






step 15



step 16



step 17



step 18

