


HOGYME

User Manual

Instruction for Assembly 6' * 8' Metal Shed



Missing Parts, Quality Problem, Questions on Assembly?
Email: Hogyme.service@gmail.com
Request will be replied in 24 hours.

Model Number : HG61U0559
HG61N0662
HG61S0665
HG61P0735

HOGYME

Assembly Preparation

Owner's Manual

Please check local building codes regarding footings, location and other requirements before beginning construction.

Assembly instructions:

Reviewing all instructions and the appropriate information before you begin, make sure following the step sequence carefully for successful results.

Flooring base:

A good location for the storage building is a square and level area with good drainage. The base is not included in the kit which may need purchase separately or may construct a foundation and anchoring system of your own.

A strong plastic sheet (thickness: at least 150μm) should be placed under the foundation to assist in reducing rising dampness from the soil, thus reducing condensation build up in the shed. Your storage building must be anchored to prevent wind damage. Once secured, it is highly recommended applying silicone along the inside of the base rail to minimize condensation.


Parts and Parts List:

Before you start, separate and identify all the parts and hardware to be sure that you have all the necessary parts for your building (refer to the Parts List Page).

If you find that a part is missing, please notify the seller within one week after receiving the product. Do not attempt to assemble the building if parts are missing because any building left partially assembled may be seriously damaged by light winds.

Tools you need:

(Please tear off the safety protection layer before the assembly, keep the part number label if needed)




Safety must be put in the No. 1 position:

1. Select a dry and calm day for your assembly. Team works (Two or more people) are required during the assembly. It is also recommended to finish the assembly in a day to avoid damage to the product or missing of some small parts.
2. Wearing safety gloves, eye protection and long sleeves during the assembly to prevent injury. Pay attention to the sharp edge of some parts.
3. Children and pets are not allowed entering into the construction site.
4. Never concentrate your total weight on the roof of the building.
When using a step ladder make sure that it is safe.


Care & Maintenance:

1. Keep the shed clean with soft cloth, use water if necessary.
2. Keep the door tracks clear of dirt and other stuff that prevent them from sliding easily.
3. Clean the snow with necessary tools to make sure it is safe to enter into.
4. The shed is not made for living but storing stuff.
5. Please add some oil on the top and bottom door sliding channel to make door slides smoothly.



Size:






Area of installation requirement:






PRODUCT ASSEMBLY















PRODUCT ASSEMBLY










Hardware List

PART	NO.	Qty.	Box No.
	G2	4	3/3
	GB	2	1/3
	GC	4	1/3
	GD	4	1/3
	GE	2	1/3
	GF	4	1/3
	F1	308	1/3
	F2	91	1/3
	F3	8	1/3
	S1	156	1/3
	S2	251	1/3
	1	2	3/3
	3L	1	3/3
	3R	1	3/3

PART	NO.	Qty.	Box No.
	4L	1	3/3
	4R	1	3/3
	5	1	3/3
	6	1	1/3
	7	1	3/3
	8	1	3/3
	9	2	3/3
	10L	1	3/3
	10R	1	3/3
	13	4	3/3
	15	2	3/3
	16	2	3/3
	17	2	3/3
	18	2	3/3
	19	2	1/3

PART	NO.	Qty.	Box No.
	20	4	1/3
	21L	2	1/3
	21R	2	1/3
	25L	1	2/3
	25R	1	2/3
	27	2	3/3
	B1	8	3/3
	P1	2	1/3
	P2	4	2/3
	P3	12	1/3
	P4	2	2/3


PART	NO.	Qty.	Box No.
	P7	2	2/3
	P5	4	2/3
	P6	4	2/3
	D1	1	2/3
	D2	1	2/3
	A1	1	3/3
	28	2	3/3
	29	2	3/3
	30	2	3/3
	31	2	3/3

PRODUCT ASSEMBLY

⚠ Check the package contents before getting started !

STEP 1


4L		X1	4R		X1
F1		X4			



PRODUCT ASSEMBLY

STEP 2


1		X1	F1		X2
---	---	----	----	---	----



PRODUCT ASSEMBLY

STEP 3


1		X1	F1		X2
---	---	----	----	---	----



PRODUCT ASSEMBLY


STEP 4

3L		X1	3R		X1
F1		X4			




PRODUCT ASSEMBLY

STEP 5

5		}	X1	F1		X4
---	---	---	----	----	---	----



The floor frame must be level and square or holes will not align.
(Notice: Measure the floor frame diagonally. When the diagonal measurements are equal, the floor frame is square.)




PRODUCT ASSEMBLY



Make the colored side of the steel plate outward.

STEP 6


P2		X1	F1		X3
S2		X3			



PRODUCT ASSEMBLY

STEP 7


P3		X1	F1		X4
F2		X1	S2		X4



PRODUCT ASSEMBLY

STEP 8


P2		X1	F1		X3
S2		X3			



PRODUCT ASSEMBLY

STEP 9


P3		X1	F1		X4
F2		X1	S2		X4



PRODUCT ASSEMBLY

STEP 10


P2		X1	F1		X3
S2		X3			



PRODUCT ASSEMBLY

STEP 11


P3		X1	F1		X4
F2		X1	S2		X4



PRODUCT ASSEMBLY

STEP 12


P2		X1	F1		X3
S2		X3			



PRODUCT ASSEMBLY

STEP 13

P3		X1	F1		X4
F2		X1	S2		X4




PRODUCT ASSEMBLY

STEP 14

9		X1	F1		X8
S2		X8			



Put the side with fewer holes facing up.




PRODUCT ASSEMBLY

STEP 15

9		X1	F1		X8
S2		X8			



Put the side with fewer holes facing up.




PRODUCT ASSEMBLY

STEP 16

10L		X1	10R		X1
F1		X1			



Put the side with fewer holes facing up.




PRODUCT ASSEMBLY

STEP 17

F1		X6	S2		X6
----	---	----	----	---	----



Put the side with fewer holes facing up.



PRODUCT ASSEMBLY


STEP 18


7		X1	8		X1
A1		X1			



PRODUCT ASSEMBLY

STEP 19


6		X1	F1		X2
---	---	----	----	---	----



PRODUCT ASSEMBLY

STEP 20


F1		X6	S2		X6
----	---	----	----	---	----



PRODUCT ASSEMBLY

STEP 21


P3		X1	F1		X8
F2		X1	S2		X8



PRODUCT ASSEMBLY

STEP 22


P3		X1	F1		X8
F2		X1	S2		X8



PRODUCT ASSEMBLY

STEP 23


P4		X1	F1		X4
F2		X2	S2		X4



PRODUCT ASSEMBLY

STEP 24


P3		X1	F1		X8
F2		X1	S2		X8



PRODUCT ASSEMBLY

STEP 25


P3		X1	F1		X8
F2		X1	S2		X8



PRODUCT ASSEMBLY

STEP 26



P4		X1	F1		X4
F2		X2	S2		X4



PRODUCT ASSEMBLY

STEP 27


P3		X3	F1		X24
F2		X3	S2		X24



PRODUCT ASSEMBLY

STEP 28


P3		X1	F1		X10
F2		X2	S2		X10



PRODUCT ASSEMBLY



STEP 29


P1		X2	F1		X16
F2		X2	S2		X16



PRODUCT ASSEMBLY



STEP 30



25L		X1	25R		X1
F1		X12	S2		X12



PRODUCT ASSEMBLY

STEP 31



21L		X2	21R		X2
GF		X4	F2		X8



PRODUCT ASSEMBLY

STEP 32


B1		X4	F2		X8
----	---	----	----	---	----



PRODUCT ASSEMBLY

STEP 33


B1		X4	F2		X4
----	---	----	----	---	----

**x2**

PRODUCT ASSEMBLY

STEP 34


F1		X10
----	---	-----



PRODUCT ASSEMBLY

STEP 35

F1		X10
----	---	-----




PRODUCT ASSEMBLY

STEP 36

13		X2	F2		X8
----	---	----	----	---	----

 The side with holes should be face-up.




PRODUCT ASSEMBLY

STEP 37

13		X2	F2		X2
----	---	----	----	---	----




The side with holes should be face-up.



PRODUCT ASSEMBLY

STEP 38

F2		X4
----	---	----




PRODUCT ASSEMBLY



Screws on the top panel can't be fixed too tightly in the beginning, and they can only be tightened after all holes are aligned.

STEP 39


P5		X2	F1		X14
S2		X12			



PRODUCT ASSEMBLY

STEP 40


P7		X1	F1		X8
S2		X6			



PRODUCT ASSEMBLY

STEP 41


P6		X2	F1		X16
S2		X12			



PRODUCT ASSEMBLY

STEP 42


P6		X2	F1		X14
S2		X12			



PRODUCT ASSEMBLY

STEP 43


P7		X1	F1		X8
S2		X6			



PRODUCT ASSEMBLY

STEP 44


P5		X2	F1		X16
S2		X12			



PRODUCT ASSEMBLY

STEP 45


17		X2	18		X2
F1		X8	S2		X8



PRODUCT ASSEMBLY

STEP 46


15		X2	16		X2
GC		X4	F1		X18
S2		X18			



PRODUCT ASSEMBLY




STEP 47


GE		X2	19		X2
F1		X9	S2		X7



PRODUCT ASSEMBLY

STEP 48


D1		X1	20		X1
27		X1	30		X1
31		X1	F2		X3



PRODUCT ASSEMBLY

STEP 49


GD		X2	F2		X4
----	---	----	----	---	----



PRODUCT ASSEMBLY


STEP 50


29		X1	GB		X1
F2		X3			



PRODUCT ASSEMBLY

STEP 51


20		X1	28		X1
F2		X5			



PRODUCT ASSEMBLY



STEP 52


F2		X4
----	---	----



PRODUCT ASSEMBLY

STEP 53


D2		X1	20		X1
27		X1	30		X1
31		X1	F2		X3



PRODUCT ASSEMBLY

STEP 54


GD		X2	F2		X4
----	---	----	----	---	----



PRODUCT ASSEMBLY

STEP 55


29		X1	GB		X1
F2		X3			



PRODUCT ASSEMBLY

STEP 56


20		X1	28		X1
F2		X5			



PRODUCT ASSEMBLY

STEP 57



F2		X4
----	---	----



PRODUCT ASSEMBLY

STEP 58

F3		X8
----	---	----



PRODUCT ASSEMBLY

STEP 59

