



## Maintenance


1) Turn off water supply. Loosen and remove the handle set screw (C) and handle (B).



2) Remove escutcheon (E) and nut (G).



3) Remove cartridge (H and/or I) and inspect for debris. Replace cartridge if necessary.



4) Install cartridge following steps 1 & 2 in reverse.

## Troubleshooting Chart

Problem	Cause	Solution
Finish is spotting.	Elements in water supply may cause water staining on finish.	Clean finished trim area with a soft cloth using mild soap and water or a non-abrasive cleaner and then quickly rinse with water.